



Instrukcja montażu mebli

«MORTIZ»





Szafa 2DG1S










Production date
Data produkcji




Stamp of Quality Department
Pieczęć Działu Jakości

№	L, mm	B, mm	H, mm	Q	№ pack
5	1088	580	16	1	1/4
35	1088	560	16	1	1/4
57	1056	560	16	1	1/4
58	1056	560	16	1	1/4
99	1971	560	16	1	3/4
100	1971	560	16	1	3/4
137	1126	84	18	1	2/4
138	957	60	16	1	2/4
147	206	560	16	1	2/4
148	206	560	16	1	2/4
157	952	210	19	1	2/4
178	500	100	16	1	2/4
179	500	100	16	1	2/4
187	880	100	16	1	2/4
209	1684	474	19	2	4/4
257	2097	580	18	1	2/4
258	2097	580	18	1	2/4
290	1991	1082	2,5	1	2/4
312	910	505	2,5	1	3/4
550	2013	84	18	1	2/4
551	2013	84	18	1	2/4
Y2	1049			1	1/4





A1  7x34 38	A2  Ø15x12 38	B5  10x50 1	C1  8x35 48
D1  8	E2  8	H48  3	I  S4 1
L2  500 2	M5  M4x25 6	N1  6	Q  1,5x7 4
R3  3x20 40	R23  6,3x13 16	R24  7x50 8	R27  5,0x13 12
R33  4x30 12	R102  3,5x16 44	S1  4	S5  Ø18 24
U.1  45x35x15 1	U5  36x36 4	V8  2	Y1  2
Y7  1	Z27  400 1		



1

A1




7x34

A2







4 Ø15x12

C1



20 8x35 16



2

A1




7x34

A2



8 Ø15x12

C1



12 8x35

R102




8 3,5x16

Y1



2



3

C1

8x35

8

R27






5,0x13

6

Z27

400

1



4

A1






7x34

8

A2

Ø15x12

2



5


A1



7x34

14

D1



8

R23



6,3x13

16

R102



3,5x16


16

U5





36x36




4



6





7




8





I



II



A=B





9

R33







12

5






10














11

x2



12

A1  7x34 4	A2  Ø15x12 4	C1  8x35 4	H48  1	I  S4 1
M5  M4x25 2	R24  7x50 4	R27  5,0x13 6	Z27  400 1	



13

L2



500

2

R3



3x20


10

R102






3,5x16

4



C=D



14

B5



10x50

1

R102



3,5x16

4

S5



Ø18

24

U.1













45x35x15

1

Y7




1



15

H48



2

Q



1,5x7


4

M5




M4x25


4



E2




E2






I

Q



II

Q



16

